

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER

Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:			
OGM	Steve Demczak	<del></del>	

# **Inspection Report**

Permit Number:	C0070041
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, September 21, 2010
Start Date/Time:	9/21/2010 10:00:00 AM
End Date/Time:	9/21/2010 2:00:00 PM
Last Inspection:	Monday, August 23, 2010

Inspector: Steve Demczak,

Weather: Sunny, 70's

InspectionID Report Number: 2507

Accepted by: jhelfric

9/28/2010

Permitee: WEST RIDGE RESOURCES
Operator: WEST RIDGE RESOURCES

Site: WEST RIDGE MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current /	Acreages
-----------	----------

6,740.53	<b>Total Permitted</b>
30.62	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

### Mineral Ownership

# Types of Operations

<b>~</b>	Federal	$\checkmark$	Underground
<b>✓</b>	State		Surface
	County		Loadout
	Fee		Processing
	Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Dana Marelli was on inspection for the permittee.

The Permittee continues to meet this Special Condition of the current State of Utah permit to send water data electronically.

No violations were written.

Inspector's Signature:

Steph Dengt

Date

Monday, September 27, 2010

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0070041 Inspection Type: PARTIAL

Inspection Date: Tuesday, September 21, 2010

Page 2 of 3

# REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>✓</b>		<b>~</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>V</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>✓</b>		<b>~</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	<b>V</b>		<b>✓</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		<b>✓</b>	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing		. []		
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	<b>~</b>		<b>✓</b>	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other		П		

Permit Number: C0070041
Inspection Type: PARTIAL

Inspection Date: Tuesday, September 21, 2010

Page 3 of 3

## 2. Signs and Markers

The identification sign is after the main gate to the property. All information complied with the R645 Coal Rules.

# 4.a Hydrologic Balance: Diversions

The diversions and culverts have been cleaned out since the last inspection. The permittee has received a violation Nov #10065 for additional contributions of sediment into the undisturbed drainage/creek. The permittee discharged coal fines into the drainage/creek which blackened the creek bed. The permittee clean the stream from discharge culvert from mine to Pond A. The water was diverted around pond A for cleaning. Pond c and Pond E were constructed and waiting for waddles. They arrived during the inspection. The plan is continue cleaning from Pond A to Pond C. The discharge water at the main culvert looked clean.

# 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment pond did contain a small amount of water. No hazardous conditions were reported.

#### 8. Noncoal Waste

The site was clear of non-coal waste.

#### 10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

## 18. Support Facilities, Utility Installations

There were no new support facilities constructed since the last inspection.